

# Flashlights Instructions

Step 1. Feed LED into cap.  
Step 2. attach resistor to negative (long) LED wire  
Step 3. Make all other attachments as in picture.

Step 5. Tape connection between switch and red battery wire

Step 4. Solder these 3 points; cover with electrical tape.

(hook wires together and wrap)

Do NOT solder switch

1.

2.

3.

Tape down unused LED legs

(Do not lose washer and nut from switch)

